



Facility Results™

Electrical System Reliability & Safety Solutions

FlashTrack™
Change Management Compliance Tool







Managed Glove Compliance Program

Electrical Personal Protective Equipment Chart

NFPA 70E 2012 Table 130.7 (C)(16) Protective Clothing & Personal Protective Equipment (PPE)

*For More Detailed Information or Other Options Refer to NFPA 70E 2012 Edition, Table 130.7 (C)(16)

<p>Hazard/Risk Category</p> <p>0</p>	<p>Untreated natural fiber Shirt (long sleeve) Pants (long) Safety glasses Hearing protection Heavy duty Leather gloves (as needed)</p>	
<p>Hazard/Risk Category</p> <p>1</p> <p>4 cal/cm²</p>	<p>Arc-rated long-sleeve shirt Arc-rated pants or coverall Arc-rated face shield with hard hat Safety glasses Hearing protection Leather & voltage rated gloves (as needed) Leather work shoes</p>	
<p>Hazard/Risk Category</p> <p>2</p> <p>8 cal/cm²</p>	<p>Arc-rated long-sleeve shirt Arc-rated pants or coverall (New 2012) Arc-rated face shield & balacava or arc flash suit hood with hard hat Safety glasses, Hearing protection Leather & voltage rated gloves (as needed) Leather work shoes</p>	
<p>Hazard/Risk Category</p> <p>3</p> <p>25 cal/cm²</p>	<p>Arc-rated long-sleeve jacket Arc-rated pants Arc-rated flash hood with hard hat Safety glasses, Hearing protection Leather & voltage rated gloves (as needed) Leather work shoes</p>	
<p>Hazard/Risk Category</p> <p>4</p> <p>40 cal/cm²</p>	<p>Arc-rated long-sleeve jacket Arc-rated pants Arc-rated flash hood with hard hat Safety glasses, Hearing protection Leather & voltage rated gloves (as needed) Leather work shoes</p>	